

CN 01 100 1834746

Second Follow-up Audit Report as per

ISO 9001: 2015

for

Mangaldan Water District

Serafica St., Poblacion, Mangaldan, Pangasinan

Pump Stations: Pump Station No. 4 (Guilig PS), Barangay Gulig, Mangaldan and Pump Station No. 12 (Anolid PS), Barangay Anolid, Mangaldan

Audit Report



Client	Standard	Certification Number(s)	Audit Type
Mangaldan Water District	ISO 9001:2015	CN 01 100 1834746	Second Follow-up Audit

Contents

1	Audit result	3
2	Scope	
2.1	Description of the organization	
2.2	Scope of certification	4
3	Changes in the management system / Contract review	
4	Audit findings	
5	Dates	

Rev. 20200626 / MS-0015679 Page 2/12

Audit Report



Client	Standard	Certification Number(s)	Audit Type
Mangaldan Water District	ISO 9001:2015	CN 01 100 1834746	Second Follow-up Audit

Audit Leader Elisa Cruz

Audit Team Orlan Tiongzon

Client's representative Ms. Marlyn De Guzman, QMR

Audit Date 16 September 2020 - 16 September 2020

1 Audit result

Management system effectiveness was verified on site by means of random sampling by an appropriately selected audit team. This applies in particular to the compliance of workflows with standard requirements and the descriptions е g t е

statutory also takei he appro	ement system documentation. The special features of the organization's business activities, the applicable and regulatory requirements and the requirements set forth in other generally applicable documents weren into account. This was done by means of a sampling approach, by conducting interviews and reviewing priate documentation. Audit findings and recommendations regarding opportunities for improvement have forth in Sections 4 of this report.
	The last audit revealed nonconformities which have been demonstrably corrected. The corrections and corrective actions taken in this respect have been verified.
	A stage 1 audit was performed and the organization found ready for certification. Identified weaknesses, if any, have been eliminated and the respective corrective action verified.
✓	The current audit revealed Zero (0) major nonconformity and Zero (0) minor nonconformity:
	The major nonconformities (No. x) with individual standard elements require a re-audit to verify the effectiveness of the corrections and corrective actions (probable date:.ddmmyyyy)
✓	The organization has established and maintains an effective system to ensure compliance with its policy and objectives. The audit team confirms in line with the audit targets that the organization's management system complies with, adequately maintains and implements the requirements of the standard.
Γhe audit	or therefore recommends (provided nonconformity response has been approved):
	Award of the new certificates.
✓	Maintenance of the existing certification.
	Inclusion of the changes (see Section 3) in the scope of application of existing certifications
	Maintenance or issue of the certificates only after successful completion of a re-audit.

Rev. 20200626 / MS-0015679 Page 3/12